

Annexure D

BUILDING SAFETY CERTIFICATE

No. PWH/MSO/B1-1/2025-26-509 Dated: 06-10-25

It is certified that the existing building PMSRI/3TCGGSSS NURPUR (name of the building or premises) at NURPUR

(address) is having block(s)/Floor(s) as per details below:


Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ad. 2	ClassRoom 2	CR 3	CR 3	C.R. 2	Staff room 1

The building is owned/occupied by PMSRI/3TCGGSSS NURPUR (name of the institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Balvinder Singh, AE HPPWD (Name of Department/ Govt.) on 06-10-2025 (date of inspection) in the presence of Karam Chand Principal (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 1962 for a period of _____ years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 06-10-2025 at Nurpur by _____

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.


 Signature with Seal _____
Assistant Engineer
Nurpur Sub Divisor
HPPWD Nurpur
 Designation _____

Name & Address of Department/ Office: _____